


January 2008 Grid Operations

March 18, 2008

Content


- Peak Demands: Actual vs. Forecast
 On-line Resources: Total at Peak and Wind
- Load Forecast Performance
- Out of Merit Capacity Order (OOMC) & Reliability Must Run (RMR) Purchases
- Zonal Congestion
- Significant System Incidents
- Advisories, Alerts and EECPs
- Other Items

Daily Peak Demands: Hourly Average Actual vs Forecast Resource Plan: On-line Capacity at Peak





Monthly Peak Demands: Actual






Load Forecast Performance in January 2008

	Mean Absolute Percent Error (MAPE) for Mid-Term Load Forecast (MTLF) Run at 16:00 Day Ahead					
	2005 MAPE	2006 MAPE	2007 MAPE	2008 MAPE (YTD)	January 2008 MAPE	
Average Annual MAPE	4.56	3.79	3.55	3.30	3.30	

Capacity Purchases for RMR OOMC & RPRS to Manage Local Congestion in January 2008





Zonal Congestion

CSC	Jan 08 Days	Jan 07 Days	Last 12 Months Total Days
North – Houston	0	0	76
North – West	9 Jan – 8,17,22,23,24,25,26,30,31	1	43
West – North	7 Jan – 3,4,5,6,9,20,21	0	40
South - North	5 Jan – 19,21,22,23,28	0	16
North - South	8 Jan – 4,5,6,8,14,15,16,20	N/A	8

Significant System Incidents in January 2008

January 1st

New North – South CSC implemented.

January 22nd

 Trip/close of a 345 kV line in the Western zone isolated 6 units for roughly 25 cycles, 5 units totaling 420 MW tripped. Frequency recovered in 1.5 minutes.

January 29th

 Benbrook – Decordova & Everman & Parker Switch and Wolf Hollow – Rock Creek 345 kV lines and Benbrook 345/138 kV autotransformer tripped. (Not simultaneous) Reported range fires in the area.

Advisories and Alerts in January 2008

- Advisories issued for Adjusted Responsive Reserve (ARR) below 3000 MW.
 - Issued 6 Days.
- Alerts issued for ARR below 2500 MW.
 - None
- Transmission Alerts (Operation above single contingency limits):
 - None
- EECP
 - No EECPs implemented.

Other Items

December 31

 10:15 - 15:00 Day-Ahead A/S Obligations re-published due to Responsive Reserve Obligation issues. New application for 2008 was not accounted for in listing the Responsive Reserve Obligation value.

January 1

- 0:00 2:00 Eight held balancing intervals.
 - Replacement Reserve Service study failure and the held intervals were due to congestion zone changes which resulted in a duplicate record after testing.

• January 18th – 20th

 RPRS failure to meet Day-Ahead time-line. New code migration slowed down execution of RPRS.