

Valley Import Overview -- Update

Shun-Hsien (Fred) Huang Regional Planning Group Meeting August 19, 2014






Outlines


- Valley Overview 2016 Update
 - The entire Frontera Facility will not be available beginning January 1, 2016
- Preliminary PV Analysis
- Discussion and Next Steps



Valley Transmission - 2016



Valley Load Forecast (2014 RTP)





Valley Import Study

- Study Case
 - 2016 Summer Peak (SSWG, March 2014)
- Base Case Condition
 - All Valley Gas Generation at Pmax
 - Lobo North Edinburg 345 kV in service (with series capacitor)
 - North Edinburg Loma Alta (Cross Valley) 345 kV in service
 - Valley Wind Output = 10% dispatch
 - Railroad DC-Tie no import/export
 - <u>Turn off the entire Frontera Facility</u>
- Steady State PV Analysis



VSAT Results


		Valley Load (MW)	
Outage	Contingency	at Stability Limit	
N-1	N-1	2521	
G-1	G-1	2452	
N-1	G-1	2434	

Base Case Notes:

- (1) G-1includes entire combined cycle train
- (2) N-1 includes 345 kV transmission line
- (3) Dynamic analysis results (ongoing work) may show stability limits lower than in the above table



Valley Potential Gen (by County), COD by 2016



Preliminary

Discussion

- All the identified contingencies indicate the limitation to serve the projected Valley load in 2016.
- ERCOT is working on dynamic stability analysis
- ERCOT will work with area TSPs and RPG to evaluate project alternatives to address the reliability need
 - Static and/or dynamic reactive devices
 - Ajo Caballo 345 kV line (suggested in 2011 ERCOT Independent Review)
 - San Miguel Lobo North Edinburg second circuit
 - Additional import path
 - Impact of new Generation Interconnection projects
- Railroad DC tie assumption



Questions/ Comments?



VSAT Results

		Valley Load (MW)	
Outage	Contingency	at Stability Limit	Year Exceeded
N-1	N-1	2867	2020
G-1	G-1	2947	2021
N-1	G-1	3061	2022

Base Case Notes:

- (1) G-1includes entire combined cycle train
- (2) N-1 includes 345 kV transmission line
- (3) Dynamic analysis results (ongoing work) may show stability limits lower than in the above table
- (4) Frontera Facility is in service in the base case

