



Global Business Services

External Review of Nodal Program PMO Control System

Executive Discussion

Electric Reliability Council of Texas,
Inc. (ERCOT)
Board of Directors Meeting
February 19, 2008

Observations and Recommendations

- Controls in place are generally functioning as expected
- Certain control activities should be enhanced
- Recommended control enhancements can reduce risk of schedule delays and quality degradation

Certain PMO Control Areas Require More Focus

IBM Review Reports

Review Ratings


- Effective Controls
- Minor Improvements Needed
- Moderate Improvements Needed
- Significant Improvements Needed
- Unsatisfactory
- Not Evaluated

Control Activity


	Report 1	Report 2	Report 3	Report 4	Report 5	Change
Control	10 Oct 2006	15 Jan 2007			30 Jan 2008	
Scope			Scope risk is high due to non-critical changes			▶
Stakeholders						▶
Change Requests			People issues with internal to support transition			▶
People						▶
Vendors			Risk Management needs to be focused on key mitigations			▶
Risks						▶
Issues			Timeline is uncertain upstream delays and limited visibility to vendor unit testing progress			▶
Communications						▶
Timeline						▶
Technical Infra			PMO may need analytical support			▶
Deliverables						▶
Organization			Quality Management requirements tracing backlog			▶
Costs						▶
Quality						▶

Resource and Deployment


Typical milestones for transition are rapidly approaching; readiness is lagging



- ✓ Complete and Staff Transition Plans
- ✓ Fill open Nodal Consulting/Contractor Positions




Incomplete Transition Plans and No Transition Plan Staffing



Risk Management

- Over 100 items are in the file with identified high impact on the time line
- Most risk items are controllable to some degree
- Large number have mitigating actions defined
- Some risk plans need more development
- Some duplication likely exists
- ✓ ***Update the plan, focus on highest risk/controllable items and align with senior management as appropriate***


Open Risk Items as of January 18, 2008



Quality Management

- Quality Review: documentation quality, software quality and requirements traceability.
 - Reviews internal and external
 - Adherence to Nodal Protocols and requirements within the software developed involves tracing of key requirements.
 - Nodal Protocols are traced to test scripts, ending with successfully completed test scripts.
 - Uses a software requirements tracking tool – Requisite Professional (ReqPro) and a test repository - Quality Center.
 - Tracing Protocols is lagging.
- ✓ ***The Nodal Program team needs to complete this critical testing documentation.***


Protocols Traced to Test Scripts



Timeline

- Critical Path (milestone plan) managed the Delivery Assurance Group.
 - Project teams typically maintain separate work plans – not with enough detail.
 - Vendors maintain separate plans.
 - Supplemented by on personal commitments.
 - Transition from phases supported with Quality Gate reviews
 - Observable (verifiable) information is not always available.
- ✓ ***Provide greater progress visibility and intermediate milestones for vendors. Support schedule stability for FAT starts.***

Testing Process Sequence




Test Results
Not (Typically)
Visible to
ERCOT

Test Results Visible to ERCOT
(DAG Managed)

¹ Factory Acceptance Testing; ² Early Delivery Software (Testing)

PMO

- The PMO organization has experienced high turnover with reassignment staff to other Nodal Program Roles.
- Resources redeployed to support other areas when critical needs have been expressed.
- Support for PMO occurs primarily on a crisis management approach.
- The Delivery Assurance Group (DAG) is providing analytical and management support for critical path.
- This limits the effectiveness of the control system and could have reduced the degree of “fire-fighting”.
- ✓ **Assess PMO Analytical support needs in addition to DAG and “Testing Tsar” Provide more stability for this organization for requisite roles.**



Nodal Program Charter requires the PMO to deliver:

- An effective control framework
- An operational quality assurance process
- The Readiness Scorecard
- Regular and ad-hoc status reports to all governance bodies

Summary of Observations and Recommendations

Issue	Impact	Recommendation
Resource Planning and Deployment	<ul style="list-style-type: none"> ▪ ERCOT support/readiness ▪ Availability of contractors/vendor resources when transition occurs 	<ul style="list-style-type: none"> ▪ Engage executive team to address ERCOT resources to support issues ▪ Expedite process to fill open contractor positions for Nodal
Risk Management	<ul style="list-style-type: none"> ▪ Absence of viable mitigation plans ▪ Delay in reaction time with schedule impact 	<ul style="list-style-type: none"> ▪ Prioritize to top risks for action using probability and schedule impact and resolve realized risks. ▪ Assign ERCOT integration related risks to ERCOT executives outside the Nodal Team
Quality Reviews	<ul style="list-style-type: none"> ▪ Completeness not confirmed with Protocols ▪ Requirements tracing for future compliance and control 	<ul style="list-style-type: none"> ▪ Clean-up backlog of tracing (testing documentation) for software already released to FAT ▪ Place this work on a higher priority
Timeline	<ul style="list-style-type: none"> ▪ Absence of Pre-FAT visibility of vendor progress ▪ Lagging measures 	<ul style="list-style-type: none"> ▪ Consider capturing data on vendor testing prior to FAT ▪ Evaluate other information that are leading indicators of progress
PMO	<ul style="list-style-type: none"> ▪ Turnover of resources ▪ Potential lag in report ▪ Fire Fighting Mode 	<ul style="list-style-type: none"> ▪ Assess PMO analytical support needs in addition to DAG and “Testing Tsar” ▪ Provide more stability for requisite roles of this organization