

# **Nodal Program Update**

Mike Cleary
Chief Operating Officer


**ERCOT Board of Directors 20 September 2010** 



# **Nodal Go-Live Update** Certified Systems Update

Kenneth Ragsdale Principal Market Operations

# **NMMS Overview**



### Status / Other Issues:

- No major issues
  - Stability issue resolved as of July 1st (ERCOT continues to monitor production)
  - Navigation performance issues improved Aug 1st (43% reduction in response time)
  - Validation performance improved August 27th (40% reduction in validation time).

# Open Defects\*:



A Sev 2: 0

Sev 3-5: 0


# **Deferred Defects\*:**



\* As of September 10, 2010



# **OS Overview**




#### Status / Other Issues:

- All Outage scheduler issues within the TSP Issues list have either been addressed or are resolved
- Two open defects are being investigated
  - One defect is being tested in development, which does not allow a TSP to submit a group outage on a breaker that is jointly operated by a QSE.
  - Other defected is awaiting delivery from ABB



# **CRR Overview**

#### **Recommendation of Certification**



### Status / Other Issues:

- Working with Siemens on automated processor fix. Expectation is to receive fix before Go-Live
  - Processor fix is in house and being tested
  - October Auction will use manual workaround

#### **Open Defects\*:**







# **Deferred Defects\*:**



 $^{\star}$  As of September 10, 2010

