

November 24, 2011  
Resettlement

XO Energy TX LP

# Not a Software Error

Software met requirements of the Nodal Protocols  
Section 4.4.4(6)

Software met Overall Market Management System requirements  
Functional Requirement 24

"provide a clear, concise and unambiguous set of requirements [...] to allow the developer/implementer to deliver a fully operational, compliant and robust Texas Nodal System"

# Not a Data Error

Heuristic table must be predetermined by ERCOT Staff

Staff chose to include DC\_N in the heuristic table

Staff chose which nodes to include for DC\_N

Price Validation Tool did not generate any warnings or errors

Other days with same price divergence not considered "data error"

"Data error" continues to exist, according to Staff's responses

# Resettlement not valid under Protocols

No data or software error occurred

DC\_N is part of HB\_West, HB\_HUBAVG, HB\_BUSAVG  
If resettled as energized, hubs should also be resettled