Hurricane Harvey Update 10-17-2017



Hurricane Harvey

- Category 4 hurricane made landfall in the Coastal Bend area of the AEP Texas service territory on August 25th
- At peak, 220,000 outages
 - Restored power to 96% by day 14
- Tremendous support from community leaders and the public in the impacted areas
- Collaborative efforts with other Texas utilities, ERCOT and Regional Mutual Assistance Groups



HURRICANE HARVEY RECAP:

September 2017

766



downed or damaged transmission structures



distribution poles repaired or replaced



Restored power to

219,000 customers

4 million


Total feet of transmission and distribution conductor replaced approximately 712 miles




Total number of workers participating at the peak of the restoration effort

Communication Efforts

- State and Local Emergency Management coordinators and contact with key stakeholders
- Central FEMA Coordinator
- Participation in town hall and customer meetings
- Restoration updates, news releases and media interviews
- Social media Facebook, Twitter
- AEP Texas website and outage map





Non-ping meters

Pole damage

Areas impacted by Hurricane Harvey included: Corpus Christi, Port Aransas, Aransas Pass, Rockport, Fulton, Refugio, Port Lavaca, Bay City and Victoria.

Item 5.3.1 ERCOT Public







Flooding, mosquitos, as well as windy and muddy conditions created special challenges for work crews.





To address these challenges, specialized equipment and technology, such as drones, ATVs, pictometry and helicopters were utilized during the assessment and restoration efforts.

Special Thanks:

Many thanks to state and local leadership, as well as the PUCT staff for all of their help.

A special "Thanks" to the communities we serve and to the 5,600 workers who were able to restore service to 96 percent of those impacted within a two-week period of time.





Appendix



Damage Summary

TRANSMISSION:

Substations impacted/restored	68
Transmission lines locked out during storm	61
Transmission line structures downed	549
Estimated conductor replaced (miles/feet)	333 miles
	or 1.8 million feet

DISTRIBUTION:

Distribution poles damaged or replaced	5,726
Transformers damaged or replaced	1,413
Breakers that locked open	270
Estimated conductor replaced (miles/feet)	379 miles
	or 2 million feet



Tatton Substation





ERCOT Public



Item 5.3.1 ERCOT Public



When I think of the challenge that presented itself to you right after Harvey's landfall, the only adjective that comes close is herculean. The task was unimaginable, and you worked with a rapidity that was nearly miraculous. Thank you. Thanks also for providing such constant communications. You set a few standards here, and I wanted to take a moment to express my gratitude.

Facebook posting examples

Other Participants in the Restoration Effort

AEP Ohio Disaster Resource Group Pike Electric
AEP Appalachian Power Empire District Plaska

AEP Indiana Michigan Power Evers Electric Powerline Services
AEP Kentucky Power Excel Energy Power Secure

AEP Public Service Company of Oklahoma Great Southwestern ProForce
AEP Southwestern Electric Power Company Hargrave Power Inc. QUALITY POWER LINE

5 Star Higher Power Quanta Utility Services
Ameren Illinois Hugo Garcia Electric Quantum Hargroye

Ameren Illinois Hugo Garcia Electric Quantum Hargrove
Ameren Missouri INTREN Inc. R&J Environmental

Asplundh Irby Construction RS Electric Utility Services
Associated Diversified Services J F Electric Inc. Safety Management Group (SMG)

Austin Energy James Power Line SAM Flight Operations
B&B Utility Contractors Kansas City Power & Light Service Electric Company

BBC Electric Lewis Tree Service SEC - Southern Electric Corp.

BHI Energy LineTec Storm Services
Base Logistics Louisville Gas & Electric - Kentucky Utilities Sumter Utilities

Bird Electric LPE, Inc. Sun Coast Resources

Bison Electric Mammoth SUN TECH ELECTRICAL
CANFER MasTec T&D Solutions LLC

Centerpoint Mesa Line Services Tech Serv Consulting

Chain Electric Company MYR Group Texas New Mexico Power

City Public Services OG&E Electric Services UC Synergetic

CT Drilling & Construction Oncor Electric Delivery Westar

Davey Resource Group One Source Restoration Willbros T&D Services

Davey Tree Company One Source T&D William E Groves Construction Inc.

David H. Elliot Company Par Electrical Contractors Wright Tree Services

Also, many thanks to Midwest Mutual assistance Group, Texas Mutual Assistance Group and Southeastern Electric Exchange